





HIGHWAYS ELECTRICAL SERVICES

ALDBURY PARISH COUNCIL

Quote No: 10042

Your ref: G. Turczyn

Date: 31st March 2025

QUOTATION


Description:	
ALDBURY, HERTFORDSHIRE.	
Repair/replacement/upgrade of PC owned street lighting systems.	
Asset ID:	
2U156-FL-0002R – STONEYCROFT column inspection new LED lantern:	
C68-FL-0068R – STOCKS ROAD new pole mount bracket and LED lantern:	
C68-FL-0057R – NEW GROUND ROAD new pole mount bracket and LED lantern:	
C68-FL-0058R – NEW GROUND ROAD new pole mount bracket and LED lantern including	
new DNO enclosure:	
C70-FL-0065R – TOMS HILL ROAD new pole mount bracket and LED lantern:	
C70-FL-0066R – TOMS HILL ROAD new LED lantern:	
C70-FL-0064R – STATION ROAD – replace missing LED lantern:	
C70-FL-0004R – STATION ROAD – (Nr Tring Station) new pole mount bracket and LED	
lantern:	
All of the above works =	£3,688.00
Asset ID: (options for works/costings)	
C68-FL-0061R – TROOPER ROAD, supply and install.	
1. Inspect and if serviceable, convert existing fitting to an LED unit:	£105.00
2. New heritage wall bracket with new shielded drop head heritage LED lantern:	£1,170.00
3. New standard galvanised pole arm and LED lantern:	£485.00
C68-FL- 0062R & 0063R – THE GREEN New 6m galvanised column with heritage collars	
and ladder rungs, painted black – fitted with new un-shielded heritage lantern (see	
example images), control gear to include RCBO and timer with external 16amp	
commando socket, replacing wooden pole and seasonal Xmas feeder pillar:	£2,780.00
EXTRAS - Supply and installation of new 8" diameter stainless steel Christmas tree	
pit/sleeve located on THE GREEN:	£638.00
(Quotation valid for 30 days and includes removal of all risings and disposal of obsolete	
fixtures and fittings, plus a 2 year warranty on all parts and labour)	

ALDBURY LANTERN AND COLUMN EXAMPLES

For the Aldbury Green location we would recommend either the 3rd lantern from the left or the 2nd lantern from the right. These are LED warm white output and can carry gas mantle effect visual for daytime appeal.

The costing quoted for the new heritage column and matching lantern is the worst case scenario, this can be reduced depending on lantern choice.





New column example, showing collar and ladder arm embelishments.

If required, a reclaimed and refurbished 6m tall cast iron column can be supplied at extra cost.

Please contact us for further details.